

Sl. No.	AC - No.	MLA Name	Name of Work	Agency Name	Project Cost (Rs. In Lakhs)	Date of Issue	Date Of Release	Remarks
1	14	Bandana Kumari	Providing & Fixing of Lighting arrangement in Mpl Park in front of H. No.- 55, YP Block, Pitampura and in front of H. No.- 154A, BC Block, Shalimar Bagh, AC-14 under Rohini Zone.	North DMC	4.33	26.06.2014	01.07.2014	
2	14	Bandana Kumari	Providing & Fixing of Lighting arrangement in Mpl Park in front of H. No.- 39, LP Block, Pitampura, W. No.- 53 under Rohini Zone.	North DMC	3.19	26.06.2014	01.07.2014	
3	14	Bandana Kumari	Providing & Fixing of Lighting arrangement in Mpl Park in front of H. No.- 26, LP Block, Pitampura, W. No.- 53 under Rohini Zone.	North DMC	3.23	26.06.2014	01.07.2014	
4	14	Bandana Kumari	Improvement of Lighting arrangement in Mpl Parks in front of H. No.-246, 201, and 260, CD Block, Pitampura and in front of H. No.-50A & 203A, BC Block, Shalimar Bagh in AC-14 under Rohini Zone.	North DMC	4.31	26.06.2014	01.07.2014	
5	14	Bandana Kumari	Providing & fixing of SHM Light with pole in mpl. parks in front of H. No.- 47, LP Block, Pitampura and H. No.- 24B, CB Block, Shalimar Bagh in AC-14 under Rohini Zone.	North DMC	4.22	26.06.2014	01.07.2014	
6	14	Bandana Kumari	Providing & fixing of SHM Light with pole in mpl. parks in front of H. No.- 233A and H. No.- 86A, VP Block, Pitampura in Ward No-53 under Rohini Zone.	North DMC	4.26	26.06.2014	01.07.2014	
7	14	Bandana Kumari	Providing & Fixing of HPSV Street Light arrangement in Pitampura (North & South), Ambedkar Nagar, Haiderpur in AC-14 under Rohini Zone.	North DMC	4.09	26.06.2014	01.07.2014	
8	14	Bandana Kumari	Providing & Fixing of HPSV Street Light arrangement in Shalimar Bagh (North & South), Sahipur Village, Singal pur and Shalimar village in AC-14 under Rohini Zone.	North DMC	4.23	26.06.2014	01.07.2014	
9	14	Bandana Kumari	Resurfacing of Road of Police Colony Shalimar Bagh, New Delhi.	North DMC	16.54	11.08.2014	12.08.2014	
10	14	Bandana Kumari	Shifting of HT Lines from Bholuwala to Shamsanwala at Shalimar Bagh.	TPDDL	14.32	22.08.2014	25.08.2014	
11	14	Bandana Kumari	Shifting of HT Lines from Haiderpur Village Ambedkar Nagar Shalimar Bagh.	TPDDL	42.27	22.08.2014	25.08.2014	
12	14	Bandana Kumari	Construction of walkway in the park opp. H.no. 71 & 72 in BK-2 Block in Shalimar Bagh (s) in C-56 RZ.	North DMC	3.47	15.09.2014	15.09.2014	
13	14	Bandana Kumari	Pdg. And placing of RCC Benches (Chair Benches) in park under the jurisdiction of ward-56, Shalimar Bagh.	North DMC	3.08	15.09.2014	15.09.2014	
14	14	Bandana Kumari	Providing and fixing a welcome board near Shalimar village at Maharaja Agrasen Marg.	PWD	9.97	24.09.2014	26.09.2014	
15	14	Bandana Kumari	Re-modeling to drainage system from H.No. JP-107 to Flat No. HP-148(both sides) and providing RMC in the lane from H.no. JP 107 to flat No. HP-148 in Pitampura (south) in C-53/RZ.	North DMC	31.1	24.09.2014	26.09.2014	
16	14	Bandana Kumari	Remodeling to drainage system from 19A to 118A , 18A to 119A 7A to 130A, 6A to 131A, and providing RMC in the lane from flat No. 19A to 118A and 7A to 130A in AD Block, Pitampura (south) in C-53/RZ.	North DMC	34.96	24.09.2014	26.09.2014	
17	14	Bandana Kumari	Imp. Dev. Of internal roads BM (West) Block from H.no. 94 to 108, H.no. 61 to 75, H.no. 111 to 125 and H.no. 144 to 158 in C-56 in Shalimar Bagh (S).	North DMC	22.67	10.10.2014	13.10.2014	
18	14	Bandana Kumari	P/L Dense bituminous carpet on the road from corner under pass Azadpur to corner of DA Block, Shalimar Bagh.	DDA	20.01	05.11.2014	07.11.2014	
19	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) AP Block.	ECIL-Rapiscan-Ltd	3.84	13.11.2014	17.12.2014	
20	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) BM Block.	ECIL-Rapiscan-Ltd	4.62	13.11.2014	17.12.2014	
21	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) AO Block.	ECIL-Rapiscan-Ltd	2.63	13.11.2014	17.12.2014	
22	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) AM Block.	ECIL-Rapiscan-Ltd	4	13.11.2014	17.12.2014	
23	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) AE Block.	ECIL-Rapiscan-Ltd	3.9	13.11.2014	17.12.2014	
24	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) BC Block.	ECIL-Rapiscan-Ltd	3.84	13.11.2014	17.12.2014	
25	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) BH Block.	ECIL-Rapiscan-Ltd	3.84	13.11.2014	17.12.2014	
26	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) MD Block.	ECIL-Rapiscan-Ltd	4.05	13.11.2014	17.12.2014	
27	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) TP Block.	ECIL-Rapiscan-Ltd	3.84	13.11.2014	17.12.2014	
28	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) Vaishali.	ECIL-Rapiscan-Ltd	3.43	13.11.2014	17.12.2014	
29	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) ED Block.	ECIL-Rapiscan-Ltd	2.61	13.11.2014	17.12.2014	
30	14	Bandana Kumari	SITC(Supply, Installation of analogue cameras/CCTV) BB Wing.	ECIL-Rapiscan-Ltd	2.18	13.11.2014	17.12.2014	
31	14	Bandana Kumari	Providing and placing of precast RCC benches in various parks AC Block in Shalimar Bagh ward no. C-56/RZ.	North DMC	4.27	13.11.2014	17.12.2014	
32	14	Bandana Kumari	P/F precast R.C.C slab/grating on drains & providing and fixing name/boards in AC block in Shalimar bagh no. 56/RZ.	North DMC	4.31	13.11.2014	17.12.2014	
33	14	Bandana Kumari	Providing & fixing of SHM Light with pole in mpl. Parks in front of H.no. SD-258 and kunj park in Vaishali, Pitampura, wino. 54 under Rohini Zone.	North DMC	4.89	13.11.2014	17.12.2014	
34	14	Bandana Kumari	Providing & fixing of lighting arrangement in Mpl parks in front of H.no. NP-136, SD-305, & NP-55 Pitampura, ward no. 53 under Rohini Zone.	North DMC	9.52	13.11.2014	17.12.2014	

Sl. No.	AC . No.	MLA Name	Name of Work	Agency Name	Project Cost (Rs. In Lakhs)	Date of Issue	Date Of Release	Remarks
35	14	Bandana Kumari	Providing & fixing of lighting arrangement in Mpl parks infront of H.no. A-60A, DP-50, Pitampura and Central park BC (East) Block, Shalimar Bagh under Rohini Zone.	North DMC	9.43	13.11.2014	17.12.2014	
36	14	Bandana Kumari	Providing & fixing of HPSV Street Light arrangement in Shaliampur Bagh, Sahipur village, Pitampura (North & South) under Rohini Zone.	North DMC	2.62	13.11.2014	17.12.2014	

Total	308.07
DJB Mandatory + Relief Fund	120.00
Grand Total	428.07